	Туре	L #	Hits	Search Text	DBs	
1	BRS	L1	2	(microhole with array) and connector	USPAT; EPO; JPO; DERWENT; IBM_TDB	
2	BRS	L2	16578	holes and inserting and fixing	USPAT; EPO; JPO; DERWENT; IBM_TDB	
3	BRS	L3	3040	holes same inserting same fixing	USPAT; EPO; JPO; DERWENT; IBM_TDB	
4	BRS	L4	325	3 and (guide with holes)	USPAT; EPO; JPO; DERWENT; IBM_TDB	
5	BRS	L5	67	4 and connector	USPAT; EPO; JPO; DERWENT; IBM_TDB	
6	BRS	L6	29		USPAT; EPO; JPO; DERWENT; IBM_TDB	
7	BRS	L7	0	4 and resin and (inorganic with filler)	USPAT	
8	BRS	L8	3040	3 and (holes) same (inserting same fixing)	USPAT; EPO; JPO; DERWENT; IBM_TDB	
9	BRS	L9	0	3 and resin same (inorganic with filler)	USPAT; EPO; JPO; DERWENT; IBM_TDB	
10	BRS	L10	22739	(resin) same (inorganic with filler)	USPAT; EPO; JPO; DERWENT; IBM_TDB	
11	BRS	L11	0	3 and 10	USPAT; EPO; JPO; DERWENT; IBM_TDB	
12	BRS	L12	18	2 and 10	USPAT; EPO; JPO; DERWENT; IBM_TDB	

	Time Stamp	Comments	Error Definition	Errors
1	2003/10/15 09:31			0
2	2003/10/15 09:32			0
3	2003/10/15 09:55			0
4	2003/10/15 09:34			0
5	2003/10/15 09:34			0
6	2003/10/15 09:35			0
7	2003/10/15 09:55			0
8	2003/10/15 09:57			0
9	2003/10/15 09:57			0
10	2003/10/15 09:58			0
11	2003/10/15 09:58			0
12	2003/10/15 09:59			0

. .